



Advanced Metal Clay Series:
Resin Jewelry Using Art Clay
with Jackie Truty

FIRING SCHEDULE



Torch and Kiln Guide for Silver Rings

*You've channeled your inner ring smith to create your piece.
Now you want to make sure it is fired to perfection.
Refer to these reminders as you fire your Art Clay Silver ring
using either a butane torch or a kiln.*

Torch Firing:

- BE SAFE: Take safety precautions, including having appropriate eyewear and proper ventilation.
- PLACE your ring on the compressed refractory ceramic fiber board.
- HOLD the torch at a 45 degree angle.
- TORCH FIRE for 6 minutes, timing from the moment the entire piece reaches a salmon/peachy glow. (Every 10 grams of silver needs to be fired for 3 minutes.)



Kiln Firing:

- PLACE your ring on the compressed refractory ceramic fiber board.
- INSERT the fiber board with ring into a cold kiln.
- RAMP the kiln as fast as it will go to 1600 degrees F
- FIRE for 10 minutes.
- REMOVE the board and let your piece cool.

Now you're ready to add the UV resin and cure it!